CITROËN C3 124811 18/11/2015

MAKE	MODEL	MILEAGE	OPERATING_HOURS
CITROËN	**C3**	**124811**	

FIRST_REGISTRATION_DATE_YEAR

18/11/2015

OVERALL_COMMENTS



DONE_ON

19/08/2026

DONE_LOCATION

DÉPARTEMENT DU LOT-ET-GARONNE, 76 ROUTE D'AGEN, 47310 ESTILLAC - FRANCE

https://rapport-trustoo.web.app/6fedc4cc-12c2-4775-9f90-ba730875003a

Catégorisation

Descriptifs essentiels

Descriptifs additionnels

Documents

Photos extérieur

Photos intérieur

Photos supplémentaires

Dommages

Conclusion

CATÉGORISATION

Catégorisation

PRODUCT_CATEGORY	VEHICLE
PRODUCT_SUBCATEGORY	Voiture
SELLER_IDENTIFICATION	VLC356KT

DESCRIPTIFS ESSENTIELS

Descriptifs essentiels

MAKE	Citroën
MODEL	C3
FIRST_REGISTRATION_DATE_YEAR	18/11/2015
SERIAL_NUMBER	VF7SCBHY6FW664193
REGISTRATION_NUMBER	DX-356KT
ENERGY	GO
TRANSMISSION_TYPE	MANUAL_TRANSMISSION
TRANSMISSION	Traction
RUNNING_GEAR_CONDITION	Bon état
VEHICLE_OPTIONS	Climatisation / TPMS / GPS / Radars de recul
SEATING_CAPACITY	5
VEHICLE_CONDITION_SUMMARY	Défaut moteur - Antipollution / Défaut feux stop ARG
INSTRUCTIONS_VEHICLE_DRIVABLE	
INSTRUCTIONS_ENGINE_RUNNING_VEHICLE_NOT_DRIVABLE	
INSTRUCTIONS_VEHICLE_NOT_DRIVABLE	

VEHICLE_DRIVABLE	VEHICLE_DRIVABLE
INSTRUCTIONS_VEHICLE_TOWABLE	
VEHICLE_TOWABLE	
INSTRUCTIONS_VEHICLE_DRIVABLE_INFORMATION	
VEHICLE_DRIVABLE_INFORMATION_SOURCE	INFORMATION_VERIFIED_DURING_INSPECTION

DESCRIPTIFS ADDITIONNELS

Descriptifs additionnels

VEHICLE_TYPE	Voiture particulière
NUMBER_OF_DOORS	5
TIRES_SIZE	185/65R15
TIRES_CONDITION	Bon état
BODYWORK_CONDITION	État moyen
UNDERBODY_CONDITION	Bon état
INTERIOR_CONDITION	Bon état
TRANSMISSION	Bon état
NUMBER_OF_GEARS	5

DOCUMENTS

Documents

REGISTRATION_CERTIFICATE_PRESENTED	NOT_PRESENTED
REGISTRATION_CERTIFICATE_PICTURE	
TECHNICAL_CONTROL_PICTURE	



SPEED_LIMITER_CERTIFICATE_PICTURE	
TACHOGRAPH_CERTIFICATE_PICTURE	
VEHICLE_TYPE_APPROVAL_CERTIFICATE_PICTURE	
VEHICLE_SPECIFICATION_SHEET_PICTURE	
CONVERSION_CERTIFICATE_PICTURE	
LATEST_PERIODIC_INSPECTION_CERTIFICATE_PICTURE	

CERTIFICATE_OF_CONFORMITY_PICTURE

OTHER_DOCUMENT_PICTURE



PHOTOS EXTÉRIEUR

Photos extérieur

34_FL_VIEW



34_FR_VIEW



34_RR_VIEW



34_RL_VIEW



ENGINE_COMPARTMENT_PICTURE



EXCAVATOR_BOOM_OR_ARM_PICTURE

HYDRAULIC_SYSTEMS_PICTURE

TIRES_OR_TRACKS_PICTURES









OTHER_EXTERIOR_PICTURE



PHOTOS INTÉRIEUR

Photos intérieur

DASHBOARD_DISPLAYING_MILEAGE_PICTURE



MILEAGE	124811
HOUR_METER_PICTURE	
OPERATING_HOURS	

DASHBOARD_PICTURE



CENTER_CONSOLE_PICTURE



TACHOGRAPH_MILEAGE_PICTURE

DRIVERS_CAB_PICTURE



FRONT_SEATS_PICTURE





REAR_SEATS_PICTURE





TRUNK_PICTURE



REAR_CARGO_AREA_PICTURE

OPTIONAL_EQUIPMENT_AND_FEATURES_PICTURE





OTHER_INTERIOR_PICTURE

PHOTOS SUPPLÉMENTAIRES

Photos supplémentaires

MANUFACTURER_IDENTIFICATION_PLATE_PICTURE



WEIGHT_PLATE_PICTURE

EQUIPMENTS_MANUFACTURERS_PLATE_PICTURE

SPECIALIZED_EQUIPMENTS_PICTURE

DOMMAGES

Dommages

DAMAGE_1_PICTURES





DAMAGE_2_PICTURES











DAMAGE_3_PICTURES



DAMAGE_4_PICTURES






trustoo

DAMAGE_5_PICTURES








trustoo


trustoo


trustoo


trustoo


DX-356-K






DX-356-KT


trustoo
trustoo


trustoo

DAMAGE_6_PICTURES






trustoo
trustoo

DAMAGE_7_PICTURES







trustoo

DAMAGE_8_PICTURES









DAMAGE_9_PICTURES

DAMAGE_10_PICTURES

CONCLUSION

Conclusion

OVERALL_COMMENTS

ADDITIONNAL_PHOTOS