PEUGEOT 206+ 303600 28/02/2012

MAKE	MODEL	MILEAGE	OPERATING_HOURS
PEUGEOT	**206+**	**303600**	

FIRST_REGISTRATION_DATE_YEAR

28/02/2012

OVERALL_COMMENTS



DONE_ON

12/08/2026

DONE_LOCATION

DÉPARTEMENT DU LOT-ET-GARONNE, 76 ROUTE D'AGEN, 47310 ESTILLAC - FRANCE

https://rapport-trustoo.web.app/01551fc1-ec5a-499f-a3c6-b4f37e28e545

Catégorisation

Descriptifs essentiels

Descriptifs additionnels

Documents

Photos extérieur

Photos intérieur

Photos supplémentaires

Dommages

Conclusion

CATÉGORISATION

Catégorisation

PRODUCT_CATEGORY	VEHICLE
PRODUCT_SUBCATEGORY	Voiture
SELLER_IDENTIFICATION	VLP644BC

DESCRIPTIFS ESSENTIELS

Descriptifs essentiels

MAKE	Peugeot
MODEL	206+
FIRST_REGISTRATION_DATE_YEAR	28/02/2012
SERIAL_NUMBER	VF32L8HR0CY016510
REGISTRATION_NUMBER	CC-644-BC
ENERGY	GO
TRANSMISSION_TYPE	MANUAL_TRANSMISSION
TRANSMISSION	Avant
RUNNING_GEAR_CONDITION	État moyen
VEHICLE_OPTIONS	Climatisation / véhicule société
SEATING_CAPACITY	2
VEHICLE_CONDITION_SUMMARY	Véhicule ne démarre pas - plus de batterie
INSTRUCTIONS_VEHICLE_DRIVABLE	
INSTRUCTIONS_ENGINE_RUNNING_VEHICLE_NOT_DRIVABLE	
INSTRUCTIONS_VEHICLE_NOT_DRIVABLE	

VEHICLE_DRIVABLE	VEHICLE_NOT_DRIVABLE
INSTRUCTIONS_VEHICLE_TOWABLE	
VEHICLE_TOWABLE	VEHICLE_TOWABLE
INSTRUCTIONS_VEHICLE_DRIVABLE_INFORMATION	
VEHICLE_DRIVABLE_INFORMATION_SOURCE	INFORMATION_VERIFIED_DURING_INSPECTION

DESCRIPTIFS ADDITIONNELS

Descriptifs additionnels

VEHICLE_TYPE	Voiture particulière
NUMBER_OF_DOORS	3
TIRES_SIZE	175/65R14
TIRES_CONDITION	Bon état - pneu ARD dégonflé
BODYWORK_CONDITION	Mauvais état
UNDERBODY_CONDITION	Bon état
INTERIOR_CONDITION	Mauvais état
TRANSMISSION	Bon état
NUMBER_OF_GEARS	5

DOCUMENTS

Documents

REGISTRATION_CERTIFICATE_PRESENTED	NOT_PRESENTED
REGISTRATION_CERTIFICATE_PICTURE	
TECHNICAL_CONTROL_PICTURE	



SPEED_LIMITER_CERTIFICATE_PICTURE	
TACHOGRAPH_CERTIFICATE_PICTURE	
VEHICLE_TYPE_APPROVAL_CERTIFICATE_PICTURE	
VEHICLE_SPECIFICATION_SHEET_PICTURE	
CONVERSION_CERTIFICATE_PICTURE	
LATEST_PERIODIC_INSPECTION_CERTIFICATE_PICTURE	

CERTIFICATE_OF_CONFORMITY_PICTURE

OTHER_DOCUMENT_PICTURE



PHOTOS EXTÉRIEUR

Photos extérieur

34_FL_VIEW



34_FR_VIEW



34_RR_VIEW



34_RL_VIEW



ENGINE_COMPARTMENT_PICTURE



EXCAVATOR_BOOM_OR_ARM_PICTURE

HYDRAULIC_SYSTEMS_PICTURE

TIRES_OR_TRACKS_PICTURES









OTHER_EXTERIOR_PICTURE

PHOTOS INTÉRIEUR

Photos intérieur

DASHBOARD_DISPLAYING_MILEAGE_PICTURE



MILEAGE	303600
HOUR_METER_PICTURE	
OPERATING_HOURS	

DASHBOARD_PICTURE



CENTER_CONSOLE_PICTURE





TACHOGRAPH_MILEAGE_PICTURE

DRIVERS_CAB_PICTURE



FRONT_SEATS_PICTURE





REAR_SEATS_PICTURE

TRUNK_PICTURE



REAR_CARGO_AREA_PICTURE

OPTIONAL_EQUIPMENT_AND_FEATURES_PICTURE

OTHER_INTERIOR_PICTURE

PHOTOS SUPPLÉMENTAIRES

Photos supplémentaires

MANUFACTURER_IDENTIFICATION_PLATE_PICTURE



WEIGHT_PLATE_PICTURE



EQUIPMENTS_MANUFACTURERS_PLATE_PICTURE

SPECIALIZED_EQUIPMENTS_PICTURE

DOMMAGES

Dommages

DAMAGE_1_PICTURES





DAMAGE_2_PICTURES












DAMAGE_3_PICTURES













DAMAGE_4_PICTURES



DAMAGE_5_PICTURES






trustoo






trustoo


0 1 2 3 4 5 6 7
0 1 5 6 7 8

DAMAGE_6_PICTURES






LOT-ET-GARON




trustoo




trustoo



trustoo


PEUGEOT
F
CC-644-BC
47


trustoo
0 1 2 3 4 5 6 7 8 9 10
trustoo
0 1 2 3 4 5 6 7 8 9 10


0 1 2 3 4 5 6 7 8 9 10
trustoo
0 1 2 3 4 5 6 7 8 9 10

DAMAGE_7_PICTURES








LOT-ET-GARONNE
Le Département


trustoo


trustoo




trustoo
trustoo

DAMAGE_8_PICTURES





DAMAGE_9_PICTURES

DAMAGE_10_PICTURES

CONCLUSION

Conclusion

OVERALL_COMMENTS

ADDITIONNAL_PHOTOS