PEUGEOT RIFTER 124439 30/09/2019

MAKE	MODEL	MILEAGE	OPERATING_HOURS
PEUGEOT	**RIFTER**	**124439**	

FIRST_REGISTRATION_DATE_YEAR	OVERALL_COMMENTS
30/09/2019	



DONE_ON

18/08/2026

DONE_LOCATION

DÉPARTEMENT DU LOT-ET-GARONNE, 76 ROUTE D'AGEN, 47310 ESTILLAC - FRANCE

https://rapport-trustoo.web.app/10e2a43c-f092-41b3-8759-2d1324dafe39

Catégorisation

Descriptifs essentiels

Descriptifs additionnels

Documents

Photos extérieur

Photos intérieur

Photos supplémentaires

Dommages

Conclusion

CATÉGORISATION

Catégorisation

PRODUCT_CATEGORY	VEHICLE
PRODUCT_SUBCATEGORY	Voiture
SELLER_IDENTIFICATION	VLP472ML

DESCRIPTIFS ESSENTIELS

Descriptifs essentiels

MAKE	Peugeot
MODEL	Rifter
FIRST_REGISTRATION_DATE_YEAR	30/09/2019
SERIAL_NUMBER	VR3ERHNP2LJ753017
REGISTRATION_NUMBER	FR-472-ML
ENERGY	ES
TRANSMISSION_TYPE	MANUAL_TRANSMISSION
TRANSMISSION	Avant
RUNNING_GEAR_CONDITION	Bon état
VEHICLE_OPTIONS	Climatisation / radars de recul
SEATING_CAPACITY	5
VEHICLE_CONDITION_SUMMARY	
INSTRUCTIONS_VEHICLE_DRIVABLE	
INSTRUCTIONS_ENGINE_RUNNING_VEHICLE_NOT_DRIVABLE	
INSTRUCTIONS_VEHICLE_NOT_DRIVABLE	

VEHICLE_DRIVABLE	VEHICLE_DRIVABLE
INSTRUCTIONS_VEHICLE_TOWABLE	
VEHICLE_TOWABLE	
INSTRUCTIONS_VEHICLE_DRIVABLE_INFORMATION	
VEHICLE_DRIVABLE_INFORMATION_SOURCE	INFORMATION_PROVIDED_BY_SELLER

DESCRIPTIFS ADDITIONNELS

Descriptifs additionnels

VEHICLE_TYPE	Voiture particulière
NUMBER_OF_DOORS	5
TIRES_SIZE	215/65R16
TIRES_CONDITION	Bon état
BODYWORK_CONDITION	Mauvais état
UNDERBODY_CONDITION	Bon état
INTERIOR_CONDITION	État correct
TRANSMISSION	Bon état
NUMBER_OF_GEARS	6

DOCUMENTS

Documents

REGISTRATION_CERTIFICATE_PRESENTED	NOT_PRESENTED
REGISTRATION_CERTIFICATE_PICTURE	
TECHNICAL_CONTROL_PICTURE	



SPEED_LIMITER_CERTIFICATE_PICTURE	
TACHOGRAPH_CERTIFICATE_PICTURE	
VEHICLE_TYPE_APPROVAL_CERTIFICATE_PICTURE	
VEHICLE_SPECIFICATION_SHEET_PICTURE	
CONVERSION_CERTIFICATE_PICTURE	
LATEST_PERIODIC_INSPECTION_CERTIFICATE_PICTURE	

CERTIFICATE_OF_CONFORMITY_PICTURE

OTHER_DOCUMENT_PICTURE

PHOTOS EXTÉRIEUR

Photos extérieur

34_FL_VIEW



34_FR_VIEW



34_RR_VIEW



34_RL_VIEW



ENGINE_COMPARTMENT_PICTURE



EXCAVATOR_BOOM_OR_ARM_PICTURE

HYDRAULIC_SYSTEMS_PICTURE

TIRES_OR_TRACKS_PICTURES









OTHER_EXTERIOR_PICTURE

PHOTOS INTÉRIEUR

Photos intérieur

DASHBOARD_DISPLAYING_MILEAGE_PICTURE



MILEAGE	124439
HOUR_METER_PICTURE	
OPERATING_HOURS	

DASHBOARD_PICTURE



CENTER_CONSOLE_PICTURE




TACHOGRAPH_MILEAGE_PICTURE

DRIVERS_CAB_PICTURE



FRONT_SEATS_PICTURE





REAR_SEATS_PICTURE





TRUNK_PICTURE



REAR_CARGO_AREA_PICTURE

OPTIONAL_EQUIPMENT_AND_FEATURES_PICTURE

OTHER_INTERIOR_PICTURE

PHOTOS SUPPLÉMENTAIRES

Photos supplémentaires

MANUFACTURER_IDENTIFICATION_PLATE_PICTURE



WEIGHT_PLATE_PICTURE

EQUIPMENTS_MANUFACTURERS_PLATE_PICTURE

SPECIALIZED_EQUIPMENTS_PICTURE

DOMMAGES

Dommages

DAMAGE_1_PICTURES















DAMAGE_2_PICTURES





DAMAGE_3_PICTURES






trustoo






trustoo


trustoo




FR-472-ML


trustoo
trustoo


trustoo




F
FR-4


trustoo




trustoo


trustoo



trustoo
trustoo


trustoo


trustoo


trustoo


trustoo


trustoo
trustoo



DAMAGE_4_PICTURES





DAMAGE_5_PICTURES



DAMAGE_6_PICTURES



DAMAGE_7_PICTURES

DAMAGE_8_PICTURES

DAMAGE_9_PICTURES

DAMAGE_10_PICTURES

CONCLUSION

Conclusion

OVERALL_COMMENTS

ADDITIONNAL_PHOTOS